

Work Order ID 55842

February 3, 2010 10:46:58 AM



Page 1

Item ID: D3265-1

Accept



Setup Start



Revision ID:

Stop



Item Name: Rib

Start Date: 2/03/10 Start Qty: 4.00



Cust Item ID:

Required Date: 2/09/10 Req'd Qty: 4.00



Customer:

Reference:

Run Start



Approvals: Process Plan: [Signature] Date: 10-2-03

Tooling: _____ Date: _____

QC: _____ Date: _____

SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3265	Rev C

100		0.00							
	Large Fab								
Large Fab	Memo	0.00							
Large Fab	1- cut D3265-1 rib as per dwg 2- remove identification markings 3- deburr		SAD	10-02-05					

(4)

110		0.00							
	QC5- Inspect part completeness to step on W/O								
QC	Memo	0.00							
Quality Control									

SAD 10-02-05

(74)

120		0.00							
	Identify as per dwg & Stock Location: <u>WA</u>								
Packaging	Memo	0.00							
Packaging									

SAD 10-02-08

(4)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 55842

February 3, 2010 10:46:58 AM



Page 2

Item ID: D3265-1

Accept



Setup Start



Revision ID:

Stop



Item Name: Rib

Start Date: 2/03/10 Start Qty: 4.00



Cust Item ID:

Required Date: 2/09/10 Req'd Qty: 4.00



Customer:

Reference:

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run HoursDraw
NumberDraw
Rev.Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/02/09 [Signature]
mf
10-2-08

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

February 3, 2010 10:47:02 AM

Page 1

Work Order ID: 55842



Parent Item: D3265-1



Parent Item Name: Rib

Start Date: 2/03/10

Required Date: 2/09/10

Comments:

Start Qty: 4.00

Required Qty: 4.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M304TS0.750W.065		Purchased	No			100	f	329.6041	19.9116			
304 SQ Tube .75x.75x.065W												

SAD

10-02-05

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

MAT

329.6040742

113082

0.00419

113245

0.00038421

113683

155.9153

113836

173.6842

19.9116

Main Warehouse

WA

0.0000047

112398

0.0000047

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

QTY -041	PART NUMBER	DESCRIPTION
X	D3265-041	BASKET ASSEMBLY
2	D2232-3	HINGE PLATE
4	D2235-1	RIB
4	D2325	SUPPORT GUSSET
2	D2327-3	BUSHING
2	D2581	MOUNTING BRACKET
2	D3265-1	RIB
2	D3265-3	RIB
2	D3265-5	RIB
2	D3442-5	SHIM

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 33842

10-2-03

DEO ATTACHED





RELEASED



NOTES:

- 1) FRAME MATERIAL: AISI 304/316 SS, 3/4 x 3/4 x 0.065 WALL SQUARE TUBING
REF. DART SPEC M304TS0.750W.065
- 2) MESH MATERIAL: 3/4-16F EXPANDED SS
REF. DART SPEC M304EX0.75-16F
- 3) FINISH: POWDER COAT ASSEMBLY GLOSS WHITE (4.3.5.2) PER DART QSI 005 4.3
- 4) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) UNITS: INCHES UNLESS OTHERWISE NOTED
- 6) BREAK SHARP EDGES: N/A
- 7) IDENTIFICATION: N/A
- 8) WEIGHT: N/A
- 9) WELD PER DART QSI 004

C	DRAWING UPDATED TO CURRENT STANDARDS. SHT 4 ADDED. RIB MATERIAL WAS 0.060 THICK. SHT 2 ZONE D5 25.63 DIMENSION WAS 27.63.	AJS	08.08.14
B	INCORPORATED A1. ADD SHIM UNDER HINGES. ADD HOLES FOR SPLIT LID BASKETS.	PH	05.06.08
A	NEW ISSUE	CP	04.02.02
REV.	DESCRIPTION	BY	DATE
DESIGN	DS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED		DRAWING NO.	REV. C
MFG. APPR.		D3265	SHEET 1 OF 4
APPROVED		TITLE	SCALE
DE APPR.		BASKET BASE ASSEMBLY (350)	NTS
DATE	08.08.14	<small>COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.</small>	



DETAIL D C4-2
(BOTH ENDS)
SCALE 10X



BASE ASSEMBLY NOTES:

- 1) FRAME MATERIAL: SEE SHEET 1
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: N/A
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: N/A
- 8) WELD PER DART QSI 004
- 9) SKIN INSIDE SURFACE OF BASKET WITH EXPANDED STEEL MESH.
TACK WELD EACH END OF STRAND TO FRAME.
- 10) DRILL WHEN ASSEMBLING WITH D3267-041/-043 LID ONLY.


D3265-041 BASKET BASE ASSEMBLY

DESIGN	DS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. C
MFG. APPR.	<i>[Signature]</i>	D3265	SHEET 2 OF 4
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	BASKET BASE ASSEMBLY (350)	NTS
DATE	08.08.14	<small>COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL, AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.</small>	

DEO ATTACHED



RELEASED

W/O 55842



8 7 6 5 4 3 2 1



D



D3265-1 RIB

D3265-3 RIB

C



D3265-5 RIB

B

**DEO ATTACHED
RELEASED**

W/O 55842

NOTES:

- 1) FRAME MATERIAL: SEE SHEET 1
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: N/A

A

DESIGN	JB	DART AEROSPACE LTD	
DRAWN	AJS	HAWKESBURY, ONTARIO, CANADA	
CHECKED	BA	DRAWING NO.	REV. C
MFG. APPR.	BA	D3265	SHEET 4 OF 4
APPROVED	BA	TITLE	SCALE
DE APPR.	BA	BASKET BASE ASSEMBLY (350)	NTS
DATE	08.08.14	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	

8 7 6 5 4 3 2 1

DRAWING NO. D3265	TITLE BASKET BASE ASSEMBLY (350)	REV. C	DART AEROSPACE LTD ENGINEERING ORDER		D.E.O. NO. D3265-C-1	SHEET NO. SHEET 1 OF 2	SCALE NTS
DRAWN <i>PH</i>	CHECKED <i>PH</i>	MFG. APPR. <i>DD</i>	APPROVED <i>MD</i>		DE APPR. <i>MD</i>		
DATE 09.04.16	DATE 09.04.16	DATE 09.04.16	DATE 09.04.16		DATE 09.04.16		

SHEET 1, MODIFY PARTS LIST AS FOLLOWS:


IS:

QTY -041	PART NUMBER	DESCRIPTION
X	D3265-041	BASKET ASSEMBLY
3	D2235-1	RIB
2	D3929-041	GUSSET ASSEMBLY
2	D3929-042	GUSSET ASSEMBLY
4	D3442-5	SHIM


WAS:

QTY -041	PART NUMBER	DESCRIPTION
X	D3265-041	BASKET ASSEMBLY
4	D2235-1	RIB
4	D2325	SUPPORT GUSSET
2	D3442-5	SHIM

SHEET 2, MODIFY DETAIL D AS SHOWN:




RELEASED
01/04/22



DRAWING NO. D3265	TITLE BASKET BASE ASSEMBLY (350)	REV. C	DART AEROSPACE LTD ENGINEERING ORDER	D.E.O. NO. D3265-C-1	SHEET NO. SHEET 2 OF 2	SCALE NTS
DRAWN <i>13</i>	CHECKED <i>PH</i>	MFG. APPR. <i>AS</i>	APPROVED <i>HH</i>	DE APPR. <i>HH</i>		
DATE 09.04.16	DATE 09.04.16	DATE 09/04/17	DATE 09.04.17	DATE 09.04.17		


SHEET 3, MODIFY SECTION A-A AS SHOWN:

IS:



SECTION A-A AS-2
2 PL
(BOTH END RIBS)

WAS:



SECTION A-A AS-2
2 PL
(BOTH END RIBS)

RELEASED
09/04/17